



Surface Defect Report (Multi Dents/Bumps)

TITTLE or DENT Name

Report Details

Project Name	New_Window_Fuselage	Tool Number	040013-dentCHECK2	
Created By		Scan Date	16. Aug 24	Report Date 16. Aug 24
Work Order No.		Flight Hours	[FlightHours]	Registration / Tail No. [Registration]
Carrier	[Carrier]	Flight Cycle	[FlightCycles]	Serial / MSN
Comments				

Screenshot




Dent / Bump Measurement

Unit mm

ID	Defect	Deviation	Small Diameter	Big Diameter	Ratio	STRG10R - A Dist.	STRG10R - B Dist.	FR265 - A Dist.	FR265 - B Dist.	Closest Dent ID	Distance
1	Dent	-0.80	55.8	71.0	70	43.6	13.6	264.0	229.8	3	79.7
2	Dent	-0.90	66.1	73.1	73	65.4	32.0	452.6	414.0	4	44.3
3	Dent	-0.44	42.7	55.4	97	74.2	52.6	123.8	97.6	5	58.1
4	Dent	-0.11	19.4	21.3	176	122.6	112.8	519.2	511.8	2	44.3
5	Dent	-0.69	64.5	73.8	93	175.6	143.0	79.0	45.6	3	58.1

3D Dent Map of Inspected Area



2D Photo of Inspected Area (simultaneously captured)

